

Customer : Lotte Chemical Titan Sdn Bhd
Address : PLO 312, Jalan Tembaga 4, Pasir Gudang Industrial Estate, 81700 Pasir Gudang, Johor, Malaysia
Location Area : Cogen Utility Natural Gas Station

BEFORE

Gas pipeline – algae growth and corrosion

Pipeline sweating due to Nitrogen gas flowing in the pipeline



Customer : Lotte Chemical Titan Sdn Bhd
Address : PLO 312, Jalan Tembaga 4, Pasir Gudang Industrial Estate, 81700 Pasir Gudang, Johor, Malaysia
Location Area : Cogen Utility Natural Gas Station

AFTER

Start work: Tuesday 10th July 2018

End work: Wednesday 18th July 2018

Applied Protega HBF(m) – primer (grey) and GF65(m) – PU top coat (white) on live pipeline (no shutdown)



Customer : Lotte Chemical Titan Sdn Bhd
Address : PLO 312, Jalan Tembaga 4, Pasir Gudang Industrial Estate, 81700 Pasir Gudang, Johor, Malaysia
Location Area : Cogen Utility Natural Gas Station

